Further to our recent telephone conversation, I am forwarding the following information:

List of Active Self-help Transposers that we maintain:

Nestle UK Ltd
 TDG Bardon
 Bardon 22
 Beveridge Lane
 Coalville
 Leicestershire
 LE67 1FB

2. Blackburn Rovers FC Ewood Park Blackburn Lancashire BB2 4JF

3. Land Rover Group Ltd
Lode Lane
Solihull
West Midlands
B92 8NW

4. Glaxo Smith Kline Greenford Road Greenford Middlesex UB6 0HE

5. Anzani House Felixstowe West c/o Felixstowe Council

> Maintained via: The Docks Felixstowe, Suffolk IP11 3SY

6. Warrington
Bewsey Road
c/o TDG Warrington
(NB: This site not
maintained by Taylors)

Brief Descriptions:

1. Nestle, Coalville: Installed due to reflections caused by warehouse.

2. Blackburn Rovers FC: New Jack Walker Stand caused one area to be

affected by reflections and one area to be

shadowed from the Transmitter.

3. Land Rover UK: Paint Shop Building caused one area to receive

reflections and one area to be shadowed.

4. Glaxo: Buildings shadowed an area from the Main

Transmitter.

5. Felixstowe: Large cranes at Port Side, which have continuous

movement caused varying signal strength and

quality from the Main Transmitter.

We would propose to offer our clients a DTTV Survey to ascertain if the Digital services can be received as an alternative to Analogue reception from either the Main Transmitter or the Self-Help Transposer, but in certain instances this will be a problem:

(i) Blackburn Rovers FC: The majority of viewers were served by the

Darwen Transmitter prior to the Self-Help Transposer. The Darwen Transmitter does not

Broadcast DDTV.

(ii) Port of Felixstowe: The continuouse movement of the Port-side

cranes could prove problematic to an accurate

DDTV survey.

We hope this information is sufficient to your requirements and await your advice on what action should be carried out to best serve our clients.

Kind regards

Barry Kearsley For TAYLOR BROS INSTALLATIONS (BOLTON) LTD